












Assembly Instruction




Parts list


A	 ϕ 8*30	52
B	 M6*80	40
C		40
D	 M6*30	6
E		6
F	 ϕ 6*80	2
G	 ϕ 6*70	10
H	 ϕ 6*50	4
I	 ϕ 3.5*30	78
S		2

J	 ϕ 12*60	4
K		12
L		12
M		8
N	 ϕ 3.5*16	16
O	 ϕ 4*45	4
P		1
Q	$\varnothing$ 15mm 	53
R	 ϕ 7*50	12
T	 	2







STEP:1




A	 $\phi 8*30$	44
---	---	----


STEP:2




B	 M6*80	20
C		20


STEP:3




B		M6*80	12
C			12
D		M6*30	6
E			6
F		ϕ 6*80	2

STEP:4




B		M6*80	8
C			8

STEP:5





G	 $\phi 6*70$	4
---	---	---



STEP:6





R	 $\phi 7*50$	12
---	---	----


STEP:7




G	 $\phi 6*70$	6
H	 $\phi 6*50$	4
I	 $\phi 3.5*30$	8
J	 $\phi 12*80$	4

STEP:8




S		02
I	 $\phi 3.5*30$	70

STEP:9





STEP:10




A	 $\phi 8*30$	8
K		12

STEP:11






L		2
O	 $\phi 4*45$	4

STEP:12





STEP:13



L		10
M		8
N	 $\phi 3.5 \times 16$	16

STEP:14



T		02
Q	$\phi 15\text{mm}$ 	53