




A line drawing of a large, high-back office chair with a wide seat and armrests, mounted on a five-star base. Next to it is a matching ottoman with a square seat and a five-star base.



A

This diagram shows the individual parts of the office chair, labeled A through J:

- A**: The main backrest and seat cushion, featuring a central vertical seam and a horizontal seam.
- B**: The front edge of the seat cushion.
- CL**: The lower backrest cushion, which has three small circular indentations at its base.
- CR**: The side support cushion, which has a horizontal strap across its middle.
- E**: A curved metal armrest bracket with four mounting holes at its ends and a central pivot point.
- H**: A vertical metal post with a flange at the top.
- J**: A small metal connector or bush.
- G**: The five-pointed star-shaped base of the chair, with a central hub and five radiating legs.

A  x 1	B  x 1	CR  x 1
CL  x 1	E  x 1	G  x 1
H  x 1	J  x 1	K  x 1
1  x 2	3  x 6	4  x 3
5  x 3	6  x 1	7  x 1

1

G

x 1

H

x 1

J

x 1

3

B

x 1

4

M8

x 45

5

x 1

6

x 1

7

x 1

2

CR

x 1

CL

x 1

E

x 1

3

M8

x 20

6

x 1

4

K

x 1

5

7

4

M8

x 2

6

x 1

6

A

x 1

1

M8

x 25

5

x 2

6




x 1

7

x 1



8

B



8/9

895/ERATO/061125/



9/9

895/ERATO/061125/