


ARDAL

















Diagram illustrating assembly instructions and safety warnings:




- Top Warning:** A triangle with an exclamation mark points to a box containing a key icon and a crossed-out power drill icon.
- Bottom Warning:** A triangle with an exclamation mark points to a box containing an icon of a block on a mat and a crossed-out icon of a block on a surface.
- Time:** A clock icon with a circular arrow and the text "20'" below it.
- Personnel:** An icon of a person and the number "2" below it.

A	B₁	C	D	E
				
x 1	x 1	x 1	x 12	x 8






F	G₁	G₂	H	I
				
x 8	x 2	x 2	x 8	x 1

!



1



2R

E





x 4

F



x 4



2L

E





x 4






F







x 4



3R



3L



!

