




SOBRAMATI



1/4

2030/SOBRAMATI/030725/



 x 1	 x 1	 x 1
---------	---------	---------

1


x 1

x 1

x 1

The diagram shows component C being rotated and then pushed down onto the top of component A. Component B is shown above, indicating it will be attached next.

2



!

