



MK_ENR_LUXE PORTE


1


FR | Prendre deux ou trois mesures de références
Prendre en compte la dimension la plus petite

EN | Take two or three reference measurements
Take the smallest dimension into account

ES | Tome 2 o 3 medidas en lugares diferentes como referencia
Quédese con la medida más pequeña

DE | Messen Sie an zwei oder drei verschiedenen Stellen
ab und berücksichtigen Sie die kleinste Abmessung

IT | Fare due o tre misurazioni di riferimento
Considerate la misurazione più piccola per il taglio

NL | Neem twee of drie maten op
Gebruik de kleinste maat voor het inkorten


PT | Ter em conta duas das tres medidas como refere
Ter em conta a medida mais pequena

PL | Wykonać dwa lub trzy pomiarów odniesienia
Wziąć pod uwagę najniższy pomiar

CZ | Udělejte si dvě nebo tři referenční měření
Vezměte v úvahu nejmenší rozdíl






SK | Získajte dve alebo tri referenčné merania
Vezmite do úvahy najmenší rozmer

TR | Iki ya da üç referans ölçümünü alın
En küçük boyutu hesaba katın





H = mm

L = mm

2**A****B****C****3****A****B**

11 x8

12 x8

**C****D**