



SAVAR













An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a power drill should not be used for assembly.	A warning triangle icon with an exclamation mark inside.	A clock icon showing the time as approximately 1:50.
An icon showing a rectangular block on a mat with a serrated edge, and a crossed-out version of the same block, indicating that the block should be placed on the mat.	A warning triangle icon with an exclamation mark inside.	A simple icon of a person standing.

15'






1

A



A	B	C	D	H
		 <p>M8 x 25</p>		
x 1	x 4	x 16	x 16	x 1

1

<p>A</p>  <p>x 1</p>	<p>B</p>  <p>x 4</p>	<p>C</p>  <p>x 16</p>	<p>D</p>  <p>x 16</p>	<p>H</p>  <p>x 1</p>
-------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------

